

Menu

HISTORY FILE MAP for year 2002

REALTIME


PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

220.17:09-17:48: 24m degraded data and 15m 1024bps data lost due to a bad relay on the beam regulator and TGC problems at DSS-24. DR G101478 and G101479 refer.

220.18:55-23:49: 55m degraded data, 3h 59m 1024bps data and 5h 512bps playback data lost due to power supplies causing timing system noise at DSS-24, DSS-15, and DSS-25. DR G101480, G101481, and DR G101484 refer.



221.22:26-22:42: 16m 1024bps realtime and 32m 512bps playback data lost due to a procedural error at DSS-24.

(221.10:07-10:39) Receivers dropped lock due to inadvertent removal from the connection engine. DR G101486 refers.